



A319

Engine Condition Monitoring

Weekly Report

ECM-LWA-Y24/W36-MSN2954

No part of this Document should be copied or reproduced in any other way on any possible media without written permission of Aliplan S.r.l.

Via Osteria Grande 57
37066 – Sommacampagna – Verona - Italy

ECM WEEKLY REPORT

A/C Type	A/C MSN	Pos	Engine S/n	Engine Type	Last Data Date	Last Flight Date	Cr. ΔEgt	Cr. ΔN2	Cr. ΔFF	Cr. N1 Vibs	Cr. N2 Vibs	Cr. Oil Tp.	Cr. Oil Press	To.EGT	To.N1	To.N2	Oil consumpt.	CFM Alert
A319-112	2954	1	577849	CFM56-5B6/P	2024-08-31	2024-09-06	OK	OK	OK	OW	OK	OK	OK	OK	OK	OK	OK	OK
		2	577850	CFM54-5B6/P	2024-08-31	2024-09-06	OK	OK	OK	OK	OK	OW	OK	OK	OK	OK	OK	OK

Summary / Analysis / Recommendations:

ESN 577849 and ESN 577850 have been checked for primary parameters shifts from baselines and for secondary parameters limits as per approved maintenance manuals. Engine Oil Consumption reveals no shift from average values and no sudden shifts; the AMM Limits are respected.

ESN577849 (Cr. N1 Vibs):

2024-09-06: pushed LWA to Review PFR and flight crew reports to confirm tactile vibration (email 06/09/2024 h10:29). Waiting answer.
WC-EO-72-020 planned on September 14th, 2024.

2024-08-30 (email 10:10): CFM opens a new CNR 20240827015 recommending to perform again the T/S (TSM TASK 77-00-00-810-863-A "Fan Vibrations Higher than or Equal to 4 Units and less than 6 Units on Engine 1 or 2") and if N1 Vibration persists, open a CSC Case for further recommendations. WC-EO-72-020 issued to perform AMM Task 72-00-00-200-006-A Inspection/Check of Foreign Object Damage (FOD) (Bird Strike Included) and TSM TASK 77-00-00-810-863-A as suggested by CFM through CNR 20240827015.
In the meantime, asked LWA to Review PFR and flight crew reports to confirm tactile vibration (email 30/08/2024 h17:51). Waiting answer.

2024-08-22: Item reopened due to N1 vib increase again; asked CFM on 2024-08-21h 18:23 to share our intention to perform Fan Trim Balance with the EVMU (Vectorial method IAW AMM 77-32-34-750-001-A01) after a new Unbalance Acquisition on the ground (AMM77-32-34-860-043-A). Waiting answer.

ESN577850 (Cr. Oil Tp.):

2023-09-15: (email 11:30) Asked Mr.Abdulrahman in order to proceed with the TSM TASK 79-00-00-810-835-A;
2023-03-31: (email 12:50) Asked Mr.Abdulrahman in order to proceed with the TSM TASK 79-00-00-810-835-A;
2023-03-31: Mr.Essam sent the PFR: no evidence of SENSOR-TEMP, RIGHT WING TK OUTER CHANNEL A (30QJ2);
2023-03-20: LWA kindly asked Mr.Essam to provide PFR; Waiting for the PFR;
2023-03-17: No news from LWY; asked again LWA (email dated 17/03/2023 12:29);
2023-03-08: Again pushed to have PFR;
2023-03-06: No news from LWY;
2023-02-23: TS Done but no PFR Message found ;asked LWY via email to have the last PFR; waiting for those PFR to reissue another TS;
2023-02-16: Planned within February 19th, 2023 the WC-EO-79-005R00 (WC1975) to TS as per TSM Task 79-00-00-810-835-A FUEL LEVEL SENSING R OUT TEMP SENSOR 30QJ2" due to SENSOR-TEMP, RIGHT WING TK OUTER CHANNEL A (30QJ2) suspected
2023-02-03: Planned for February 12th, 2023 the WC-EO-79-005R00 (WC1975) to TS as per TSM Task 79-00-00-810-835-A FUEL LEVEL SENSING R OUT TEMP SENSOR 30QJ2" due to SENSOR-TEMP, RIGHT WING TK OUTER CHANNEL A (30QJ2) suspected
2023-01-11: Issued WC-EO-79-005R00 to TS as per TSM Task 79-00-00-810-835-A FUEL LEVEL SENSING R OUT TEMP SENSOR 30QJ2" due to SENSOR-TEMP, RIGHT WING TK OUTER CHANNEL A (30QJ2) suspected
2023-01-11: Oil Temp trend unstable, on watch for further data

ECM WEEKLY REPORT

Summary/ Analysis / Recommendations:

--

Prepared by: Francesco De Negri



Checked by: Francesco De Negri









