



**A319**

***Engine Condition Monitoring***

***Weekly Report***

***ECM-LWA-Y23/W49-MSN2878***

No part of this Document should be copied or reproduced in any other way on any possible media without written permission of Aliplan S.r.l.

Via Osteria Grande 57  
37066 – Sommacampagna – Verona - Italy

## ECM WEEKLY REPORT

| A/C Type | A/C MSN | Pos | Engine S/n | Engine Type | Last Data Date | Last Flight Date | Cr. ΔEgt | Cr. ΔN2 | Cr. ΔFF | Cr. N1 Vibs | Cr. N2 Vibs | Cr. Oil Tp. | Cr. Oil Press | To.EGT | To.N1 | To.N2 | Oil consumpt. | CFM Alert |
|----------|---------|-----|------------|-------------|----------------|------------------|----------|---------|---------|-------------|-------------|-------------|---------------|--------|-------|-------|---------------|-----------|
| A319-112 | 2878    | 1   | 577744     | CFM56-5B6/P | 2023-12-04     | 2023-12-07       | OK       | OK      | OK      | OK          | OK          | OK          | OK            | OK     | OK    | OK    | OK            | OK        |
|          |         | 2   | 577751     | CFM56-5B6/P | 2023-12-04     | 2023-12-07       | OK       | OK      | OK      | OK          | OK          | OK          | OK            | OK     | OK    | OK    | OK            | OK        |

**Summary/ Analysis / Recommendations:**

ESN 577744 and ESN 577751 have been checked for primary parameters shifts from baselines and for secondary parameters limits as per approved maintenance manuals.

# ECM WEEKLY REPORT

Summary/ Analysis / Recommendations:

|  |
|--|
|  |
|--|

Prepared by: Francesco De Negri



Checked by: Francesco De Negri









